

County MONT

Inventory # \_\_\_\_\_

Temp. Field # 66F-318-112

Architectural Data: Construction: Frame ☒ Log \_\_\_\_\_ Brick \_\_\_\_\_ Stone \_\_\_\_\_

No. of stories 1 Roof type Gable Material asphalt shingle Original? \_\_\_\_\_

Wall covering: weatherboard \_\_\_\_\_ B&B \_\_\_\_\_ Vertical board \_\_\_\_\_ None \_\_\_\_\_

Tongue and Grooved \_\_\_\_\_ Sawn \_\_\_\_\_ Other asbestos shingles

Chimney: No. 1 Location \_\_\_\_\_ Material brick

Foundation: Pier \_\_\_\_\_ Stone \_\_\_\_\_ Brick ☒ Other \_\_\_\_\_

Basic Plan rect

Architectural Notes The fact that this bldg is old has been completely obscured

Sketch Plan Below (include North, door and window locations, etc.):

