

County MONT

Inventory # _____

Temp. Field # 66F-G12-123

Architectural Data: Construction: Frame _____ Log _____ Brick ☒ Stone _____

No. of stories 2 Roof type Flat Material metal Original? _____

Wall covering: weatherboard _____ B&B _____ Vertical board _____ None _____

Tongue and Grooved _____ Sawn _____ Other _____

Chimney: No. 3 Location _____ Material _____

Foundation: Pier _____ Stone _____ Brick ☒ Other _____

Basic Plan rectangular

Architectural Notes The owner points out that interior wall (A) has very
clean plaster joints and suggests that it may have been an outside wall
at one time. Owner also notes that interior wall (B) was added after

outer wall (C) and is not bonded with (C)
Sketch Plan Below (include North, door and window locations, etc.):

Round window heads (D) suggest late construction

